tor/A	SSESSOF:	ELGANY	# 264	SHED	CO Certific	LEAD PLON PROPER SDMS	K WALLS ITE TRIM AINT WAS I	DETECTED t ID			
	SSESSOT:		# 260			-PINI - WH NO LEAD PROPER RECENTLY I	AINT WAS ITY PAINTED	DETECTED t ID			
an:			# 264			NO LEAD PROPER- CECENTLY I	AINT WAS I TY PAINTED	DETECTED t ID			
			# 260			NO LEAD PROPER- CECENTLY I	AINT WAS I TY PAINTED	DETECTED t ID			
			# 264			NO LEAD PROPER- CECENTLY I	AINT WAS I TY PAINTED	DETECTED t ID			
			[#] 260			NO LEAD PROPER- CECENTLY I	AINT WAS I TY PAINTED	DETECTED t ID			
			# 264			NO LEAD PROPER- CECENTLY I	AINT WAS I TY PAINTED	DETECTED t ID			
			# 26 ¹	47		NO LEAD PA ON PROPER RECENTLY I	AINT WAS I TY PAINTED Document	t ID			
			[#] 260			ON PROPER- RECENTLY I SDMS	PAINTED Document	t ID			
			# 260	47		ON PROPER- RECENTLY I SDMS	PAINTED Document	t ID			
			[#] 26 ⁽	47		ON PROPER- RECENTLY I SDMS	PAINTED Document	t ID			
			[#] 260	47		ON PROPER- RECENTLY I SDMS	PAINTED Document	t ID			
			# 26°	47		ON PROPER- RECENTLY I SDMS	PAINTED Document	t ID			
			# 26 ¹	47	ľ	SDMS	PAINTED	41			
			# 264	47		SDMS	Documen	41			
			# 264	47				41			
	·		# 261	47				41			
			***************************************					41			
	·			·				. .			
						-	1053658				
						-		s			
		ł		•	}						
_		<u>k</u>	,								
					t t	•					
· 		!									
	D	EI GRAIY	STREET					•			
	~		377001			· /	····	· · · · · · · · · · · · · · · · · · ·			
		Exteri	or Walls			Doo	ors/Trim				
	Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)			
<u>_</u>											
L		 	 	<u> </u>		-ļ		ļ <u></u> .			
L	Total				Total						
	10121		•		lotai	i Oidi					
_		Window Trin	n/Fascia/Soffil	•	Patios/Decks/Porches						
┢	Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)			
一		7100	1 00.0	7.0		1		7.0.0 (300.0)			
			1			 					
		!	1			1					
	Total				Total						
<u> </u>			ters/Downspo		Misc Structures/Garage/Fences)						
<u> </u>	Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)			
-			in the second	and the state of the state of	سر سامها المحاربة والم			<u> </u>			
<u> </u>				ļ		 		<u> </u>			
-			 	_		ļi					
<u>_</u>	Total	L		<u> </u>	Total	<u> </u>		<u> </u>			

LBP Assessment Results

Strata Environmental Resource

Time	Site	Component	Substrate	Side	Condition	Color	Floor	Room	Results	Depth Inde	PbC	PbC Error
8/10/2005 8:27		EXT. WALL			CRACKED	PINK	FIRST	OUTSIDE		2.88	0.01	0.02
8/10/2005 8:28					CRACKED	WHITE	FIRST	OUTSIDE		1	0	0.02
8/10/2005 8:30	1	EXT. WALL	CONCRETE		INTACT	PINK	FIRST	OUTSIDE		7.29	0.02	0.04
8/10/2005 8:31		EXT. WALL	CONCRETE	EAST	INTACT	PINK	FIRST	OUTSIDE		2.32	0.01	0.02
8/10/2005 8:32		FENCE	WOOD	NORTH	PEELING	WHITE	FIRST	OUTSIDE		1	0	0.02
8/10/2005 8:34	2647	FENCE	METAL	WEST	INTACT	WHITE		OUTSIDE	Negative	1	0	0.02
			<u></u>									
	ļ		<u> </u>					<u> </u>		ļ		· · · · · · · · · · · · · · · · · · ·
						-		ļ				
	<u> </u>					 						
						···						
	<u> </u>		 		 							
		 		 				ļ				-
	<u> </u>	 	·			 						
				 		 		 		<u> </u>		
				 		 	-	<u> </u>				
				-	 							
		<u></u>	 	 	 	 		 				
				 						 		
Note: Readings	are in mo/	cm²		 	 			 				
				 -		 	-	 				
Painted surface	s not teste	d were assesse	d to be in "int	act" cond	ition at time	of site vis	it.	-				

Property ID # 2647 / 3750 Delgany Street

